

EB05: Basic Stepper Motor Drive

COURSE MATERIALS

Panel #	Panel name
PC04	Single-Phase Power Control Panel (for 120-volt operation)
PC05	Single-Phase Power Control Panel (for 220-volt operation)
E087	Adjustable Power Supply Panel
E090	Stepper Motor and Drive Panel

In addition to the JobMaster panels, the following items are also required:

JobMaster Learning Station
DMM (Fluke Model 115 or equivalent)
Oscilloscope (BK Precision Model 2120B or equivalent)