Semiconductor Cleanroom Operation

COURSE MATERIALS

The following materials are necessary for completion of the course.

	Quantity	Note
Hardware	Cleanroom personal protective equipment (PPE)	Multiple sizes required for all PPE
	 Coveralls Nitrile gloves Face mask Shoe covers Safety glasses Bear covers Sticky mat	
	Particle counter	
	Bench	
	Cleanroom	
Software	None	
Other	Personal Computer with Internet access	